

# EXHAUST BELLOWS

LOWER MAINTENANCE COSTS WITH SOLUTIONS FROM DORMAN

## Provides Flex Point In Exhaust System Coverage for today's most in-demand applications



**674-6009**

Freightliner Cascadia 125 2010;  
Detroit DD15

The exhaust pipe bellow provides a flex point in the exhaust system between the engine and after-treatment emissions equipment. Our direct replacement exhaust pipe bellows are quality-engineered to absorb displacements, vibrations and thermal expansion from extreme exhaust temperatures. All Dorman Exhaust Pipe Bellows include all required components for a complete repair, where applicable.

- Direct replacement for a proper fit every time
- Made of durable steel for increased durability and a longer service life
- Ideal replacement to prevent exhaust leaks and loss of engine power
- This part has undergone quality testing, including vehicle try-on to meet product standards

### FAILURE MODE:

- Exhaust leaking
- Exhaust bellow cracked

### HIGHLIGHTED COVERAGE

MAKE	ENGINE	YEAR	OE NUMBER	DORMAN #
Kenworth, Peterbilt	Cummins ISX, ISX 11.9, 15.0; PACCAR PX-9 & MX & MX-13	2018-07	M663541; M664111	<b>674-6018</b>
Kenworth, Peterbilt	PACCAR MX-13	2017-16	M6670640330	<b>674-6020</b>
Kenworth, Peterbilt	Cummins ISX, ISX 11.9, 15.0; PACCAR PX-9	2017-07	M6670910320	<b>674-6021</b>
Peterbilt	PACCAR PX-8 & PX-9; Cummins ISL 8.9, ISX 11.9 & 15.0	2018-10	M6670910335	<b>674-6022</b>
Peterbilt	Cummins ISM 10.8; ISX 11.9 & 15.0	2011-08	M6661310390; M6670910405	<b>674-6023</b>
Mack MRU	Mack MP7	2018-14	22307699	<b>674-6025</b>
Mack/Volvo	Cummins ISX 15.0; Volvo D13, Mack MP8	2014-09	21428534; 21959393; 22307701	<b>674-6027</b>
Mack/Volvo	Cummins ISX 15.0; Mack MP7 & MP8	2015-11	21428536; 21959395; 22307703	<b>674-6028</b>
Mack/Volvo	Volvo D11, D13, & D16; Mack MP7 & MP8	2017-11	21533396	<b>674-6029</b>

Growing the Heavy Duty Aftermarket