REBUILD KITS for

Pre-2001 Air Engaged Fan Clutches



9500HP 9.5" HT/S Series

7500HP 7.5" S Series



9500HPX 9.5" HT/S Series

7500HPX 7.5" S Series

X	U.S. Components and U.S. Manufactured	X
X	Two Bearing Hub Design	X
X	Premium Quality Bearings	X
X	Angular Contact Bearing	X
X	Floating Return Spring vs. Captive Return Spring	X
X	Premium Quality Lining	X
NEW	Friction Plate	RESURFACED
X	Superior Fused Plate (Virgin Teflon vs. Lead)	X
X	Superior O-Rings (Viton vs. NBR)	X
3-Year/300,000 Mile	Warranty	NONE

REBUILD KITS for

Post-2001 Air Engaged Fan Clutches



Part # **14-256**Rebuilds Horton® DriveMaster® Series

Part # **4300COMX**Rebuilds Horton® DriveMaster® Series

X	U.S. Components and U.S. Manufactured	X
5,000+ In/Lbs	Engagement Torque Produced	2,500 ln/Lbs
CONICAL	Premium Quality Lining	FLAT
Х	Premium Quality Bearings	X
NEW	Friction Plate	RESURFACED
VITON	0-Rings	NBR
8-Year/300,000 Mile	Warranty	NONE

