

# KIT MASTERS FAN SPACER CROSS REFERENCE



Clutch	Clutch	Clutch	Clutch	CLUTCH OD	FAN ID	SPACER WIDTH	Kit Masters PART NUMBER	Description	Old Number
Blue Bird	-	-		1	1	1	941010100	Fan Spacer, 1" Pilot, 1" Thick	
Blue Bird	-	-		1	1	2.5	941010250	Fan Spacer, 1" Pilot, 2.5" Thick	
-	-	-	HTS	2	2	0.5	942020050HTS	Fan Spacer, HTS 2-2, 0.50	
Bendix	Gold Top	-	-	2	2	0.5	942020050GT	Fan Spacer, Bendix/GT 2-2, 0.50	
Bendix	Gold Top	Gold Top 2 Speed	HTS	2	2	0.75	942020075	Fan Spacer, Bendix/HTS/GT 2-2, 0.75	94071
Bendix	Gold Top	Gold Top 2 Speed	HTS	2	2	1	942020100	Fan Spacer, Bendix/HTS/GT 2-2, 1.00	94040
Bendix	Gold Top	Gold Top 2 Speed	HTS	2	2	1.25	942020125	Fan Spacer, Bendix/HTS/GT 2-2, 1.25	94052
Bendix	Gold Top	Gold Top 2 Speed	HTS	2	2	1.5	942020150	Fan Spacer, Bendix/HTS/GT 2-2, 1.50	
Bendix	Gold Top	Gold Top 2 Speed	HTS	2	2	1.75	942020175	Fan Spacer, Bendix/HTS/GT 2-2, 1.75	9415098
Bendix	Gold Top	Gold Top 2 Speed	HTS	2	2	2	942020200	Fan Spacer, Bendix/HTS/GT 2-2, 2.00	
Bendix	Gold Top	Gold Top 2 Speed	HTS	2	2	2.25	942020225	Fan Spacer, Bendix/HTS/GT 2-2, 2.25	94072
Bendix				2	2.56	0	942025000	Adapter, Bendix 2-256, 0.00	
Bendix	Gold Top	Gold Top 2 Speed	HTS	2	2.56	0.5	942025050	Fan Spacer, Bendix/HTS/GT 2-256, 0.50	94088
Bendix	Gold Top	Gold Top 2 Speed	HTS	2	2.56	0.75	942025075	Fan Spacer, Bendix/HTS/GT 2-256, 0.75	
Bendix	Gold Top	Gold Top 2 Speed	HTS	2	2.56	1	942025100	Fan Spacer, Bendix/HTS/GT 2-256, 1.00	
Bendix	Gold Top	Gold Top 2 Speed	HTS	2	2.56	1.25	942025125	Fan Spacer, Bendix/HTS/GT 2-256, 1.25	
Bendix	Gold Top	Gold Top 2 Speed	HTS	2	2.56	1.5	942025150	Fan Spacer, Bendix/HTS/GT 2-256, 1.50	
Bendix	Gold Top	Gold Top 2 Speed	HTS	2	2.56	1.75	942025175	Fan Spacer, Bendix/HTS/GT 2-256, 1.75	
Bendix	Gold Top	Gold Top 2 Speed	HTS	2	2.56	2	942025200	Fan Spacer, Bendix/HTS/GT 2-256, 2.00	
Bendix	Gold Top	Gold Top 2 Speed	HTS	2	2.56	2.25	942025225	Fan Spacer, Bendix/HTS/GT 2-256, 2.25	
Bendix	Gold Top	Gold Top 2 Speed	-	2.56	2.56	0.5	942525050	Fan Spacer, Bendix/GT 256-256, 0.50	94100
Bendix	Gold Top	Gold Top 2 Speed	-	2.56	2.56	0.75	942525075	Fan Spacer, Bendix/GT 256-256, 0.75	94106
Bendix	Gold Top	Gold Top 2 Speed	-	2.56	2.56	1	942525100	Fan Spacer, Bendix/GT 256-256, 1.00	94102
Bendix	Gold Top	Gold Top 2 Speed	-	2.56	2.56	1.25	942525125	Fan Spacer, Bendix/GT 256-256, 1.25	
Bendix	Gold Top	Gold Top 2 Speed	-	2.56	2.56	1.5	942525150	Fan Spacer, Bendix/GT 256-256, 1.50	94103
Bendix	Gold Top	Gold Top 2 Speed	-	2.56	2.56	1.75	942525175	Fan Spacer, Bendix/GT 256-256, 1.75	
Bendix	Gold Top	Gold Top 2 Speed	-	2.56	2.56	2	942525200	Fan Spacer, Bendix/GT 256-256, 2.00	94104
Bendix	Gold Top	Gold Top 2 Speed	-	2.56	2.56	2.25	942525225	Fan Spacer, Bendix/GT 256-256, 2.25	
-	Gold Top	-	-	2.56	2	0.5	942520050	Fan Spacer, GT 256-2, 0.50	
Bendix	Gold Top	-	-	2.56	2	0.75	942520075	Fan Spacer, Bendix/GT 256-2, 0.75	No Stock
Bendix	Gold Top	-	-	2.56	2	1	942520100	Fan Spacer, Bendix/GT 256-2, 1.00	No Stock
Bendix	Gold Top	-	-	2.56	2	1.25	942520125	Fan Spacer, Bendix/GT 256-2, 1.25	No Stock
Bendix	Gold Top	-	-	2.56	2	1.5	942520150	Fan Spacer, Bendix/GT 256-2, 1.50	94107
Bendix	Gold Top	-	-	2.56	2	1.75	942520175	Fan Spacer, Bendix/GT 256-2, 1.75	No Stock
Bendix	Gold Top	-	-	2.56	2	2	942520200	Fan Spacer, Bendix/GT 256-2, 2.00	No Stock
Bendix	Gold Top	-	-	2.56	2	2.25	942520225	Fan Spacer, Bendix/GT 256-2, 2.25	No Stock
-	-	Gold Top 2 Speed	-	5	5	0.25	945050025	Fan Spacer, GT2 5-5, 0.25	No Stock
-	Gold Top	Gold Top 2 Speed	HTS	5	5	0.5	945050050	Fan Spacer, GT 5-5, 0.50	
-	Gold Top	Gold Top 2 Speed	HTS	5	5	0.75	945050075	Fan Spacer, GT 5-5, 0.75	
-	Gold Top	Gold Top 2 Speed	HTS	5	5	1	945050100	Fan Spacer, GT 5-5, 1.00	
-	Gold Top	Gold Top 2 Speed	HTS	5	5	1.25	945050125	Fan Spacer, GT 5-5, 1.25	
-	Gold Top	Gold Top 2 Speed	HTS	5	5	1.5	945050150	Fan Spacer, GT 5-5, 1.50	
-	Gold Top	Gold Top 2 Speed	HTS	5	5	1.75	945050175	Fan Spacer, GT 5-5, 1.75	
-	Gold Top	Gold Top 2 Speed	HTS	5	5	2	945050200	Fan Spacer, GT 5-5, 2.00	